Certificate of Location of Government Corner

ID#: 830204 **Description:** 1/4 SEC COR 2 11 83 **Date Set:** 4/17/2012 **County:** Olmsted

Section: 02 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.5'
The corner falls 1' north of centerline east-west townsip road and 6' west of fence south
This corner is located by GPS measurement.

Corner History:

1854 William Yerby; 40.01 1/2 set a quarter section post in mound of earth & sod. Deposited charcoal, made trench, pits, and planted osage orange seed on N & S.

7-12-2007 County Surveyor visited area and did not find anything.

10-5-2011 County survey crew dug for the 1854 quarter section post. The excavation was 6' north-south x 14' east-west. The excavation covered the centerline of the east-west township road, in line with fence south, and also the lost position (M&L) between section corners. Found a few stones down 2.8'. Cleared the stones and found a 3" diameter x 2.8' long, pointed wood post with the top being 3.2' below the road surface. The bottom point of the post extended 1.2' down into clean clay. Tied out and removed the post.

4-17-2012 County survey crew set telspar pipe with cast iron cap at the location of the wood post found previously on 10-5-2011.