Certificate of Location of Government Corner

ID#: 830304 **Description:** 1/4 SEC COR 3 10 83 **Date Set:** 6/19/2012 **County:** Olmsted

Section: 03 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.8'
The corner falls in the centerline of the road and in line with fences north and south
This corner is located by GPS measurement

Corner History:

5-1854 W. Yerby 40.0 set a charred 1/4 section post in mound of earth & sod. Made trench, pits, and planted osage orange seeds on E & W sides of trench.

4-1872 Hunter, unrecorded No.126; Dug for corner and found nothing. Doasdell avers fences N & S on line & corner posts midway. Set stone as corner.

7-12-2007 County survey crew visited area, did not find anything.

9-28-2011 County survey crew dug for the 1854 quarter section post or 1872 stone. The excavation was 10' x 10' with a depth of 6'. The excavation covered the centerline of the east-west township road, in line with fences north and south, and also the lost position (M&L) between section corners. Found nothing. Additional details regarding the dig can be found in the 2011 Remonumentation book.

6-19-2012 Having found no survey monuments, Joel Thoreson, County Surveyor, decided the centerline of road E-W and in line with fences north and south is the best perpetuation of the original corner location. Olmsted County survey crew set a 5' telspar pipe with cast iron cap, down 0.8', at said location.