Certificate of Location of Government Corner

ID#: 830404 **Description:** 1/4 SEC COR 4 9 83 **Date Set:** 7/6/2012 **County:** Olmsted

Section: 04 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.5'
The corner falls in the centerline of E-W township road and in line with fences north & south.
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes: Wm. Yerby; 40.00 set a charred quarter post in mound of earth and sod, made trench & pits, planted osage orange seed on east and west side of trench.

10-18-2007 County survey crew visited area, did not find anything.

10-11-2011 County survey crew dug for the 1854 quarter section post. The excavation was 13' north-south x 10' east-west with a depth of 3'. The excavation covered the centerline of the east-west township road, in line with fences north and south, and also the lost position (M&L) between section corners. Found pieces of wire and wood but no survey monuments. Additional details regarding the dig can be found in the 2011 Remonumentation book.

7-6-2012 Having found no survey monuments, Joel Thoreson, County Surveyor, decided the centerline of road E-W and in line with fences north and south is the best perpetuation of the original corner location. Olmsted County survey crew set a 5' telspar pipe with cast iron cap, down 0.5', at said location.