Certificate of Location of Government Corner

ID#: 830406 **Description:** 1/4 SEC COR 4 5 83 **Date Set:** 7/6/2012 **County:** Olmsted

Section: 04 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.5'
The corner falls in centerline of N-S township road and in line with fences east & west
This corner is located by GPS measurement

Corner History:

1854 Gov't notes, William Yerby; 40.0 set a quarter post. Made a mound of earth and sod deposited charcoal, made trench with pits, and planted osage orange seed E & W. 65.50 enter timber E & W.

10-18-2007 County Surveyor visited area, did not find anything.

10-10-2011 County survey crew dug for the 1854 quarter section post. The excavation was 10' north-south x 6' east-west with a depth of 6.5'. The excavation covered the centerline of the north-south township road, in line with fences east and west, and also the lost position (M&L) between section corners. Found nothing. Additional details regarding the dig can be found in the 2011 Remonumentation book.

7-6-2012 Having found no survey monuments, Joel Thoreson, County Surveyor, decided the centerline of road N-S and in line with fences east and west is the best perpetuation of the original corner location. Olmsted County survey crew set a 5' telspar pipe with cast iron cap, down 0.5', at said location.