Certificate of Location of Government Corner

ID#: 830505 **Description:** SEC COR 5 6 7 8 83 **Date Set:** 6/9/2000 **County:** Olmsted

Section: 05 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' east of centerline of TH 63, 6' north of centerline of twp road east and 4' north of fence west
County Survey Disk in S side CP WSW 74.79'
County Survey Disk in S side PP #35234 SW 77.99'
County Survey Disk in N side PP #47188 SE 90.51'
Ref pipe NE 87.05'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes William B. Yerby, Deputy Surveyor
North between sections 7 and 8. 80.00 chs. Set a charred sec. cor. post in mound for cor. to secs. 5,6,7 & 8 and made trench & pits & planted Osage Orange seed on N.E. & S.W. sides of trench.

5-1858 H. M. McDougall, Surveyor, (Old Road Book--Road No. 107) surveyed the road between Sections 5 and 6 and Sections 7 and 8.

7-1867 H. E. Horton, Surveyor, surveyed the Farmington Cemetary in the N.W. 1/4 Sec. 8, the North line of which is parallel to and 33' South of the North line of the N.W. 1/4 Sec. 8. All cemetery lines are parallel or at right angles to the North line of the N.W. 1/4 Sec. 8. He set a stone 9' South and 22' East of the N.W. corner of the cemetery, a stone 9' North and 22' East of the S.W. corner of the cemetery, and a stone 9' South and 22' West of the N.E. corner of the cemetery. The N.W. corner of the cemetery was 943.56 feet Easterly of Sec. Cor. 5-6-7-8.

10-1883 Thomas Hunter, Surveyor, surveyed the First Addition to the Farmington Cemetery.

9-1966 John Kerr, County Surveyor, (Kerr Book 94, Page 59) used a point for this corner at the intersection of T.H. 63 and the line projected from 1/4 Cor. 5-8 (found this survey) over a point 33' North of the cemetery (Card says 241' North of the S.W. corner post of cemetery--the depth of Hunter's addition was 243'). The corner came in line with the fence running West.

7-31-1980 County Surveyor found Horton's stones set 9' South and 22' East of the original N.W. cemetery corner and 9' North and 22' East of the original S.W. cemetery corner. The stone 9' South and 22' West of the N.E. corner of the cemetery is gone. We set a point on the line projected from the S'ly stone found over the N'ly stone found and 42.0 North of the N'ly stone as a point on the North line of the N.W. 1/4 Section 8.

8-11-1980 County Surveyor set a 1" square by 19" pipe with cap as Section Corner 5-6-7-8 on line from 1/4 Cor. 5-8 over the point set on the North line of the N.W. 1/4 Sec. 8 7-31-1980 and 965.56 feet (943.56 + 22) West of said point. The point came in the centerline of T.H. 63 and 4' North of the fence West and 7' North of the centerline of the road East. RPs-Yard fence - C.S. Disc in south side corner post W.S.W. 74.99, C.S. Disc in South side pp# 35234 SW 77.99, C.S. Disc in North side pp #47188 SE 90.51.

M.H.D. assumed this corner at the "intersection of roads". Their corner was 2' South of the centerline of the road East and in line with the school yard fence West.

7-26-1999 County Surveyor found 1" square pipe w/cap in good condition with mashed cap. Set ref pipe and made ties.

6-9-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

3-12-2007 County Surveyor found 1" square pipe w/busted cap at surface in good condition. Replaced cap.

10-18-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.