Certificate of Location of Government Corner

ID#: 830506 **Description:** 1/4 SEC COR 5 6 83 **Date Set:** 9/5/2012 **County:** Olmsted

Section: 05 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.1'
The corner falls 14' south of centerline of northerly residential drive east and 39' east of centerline of TH Highway No. 63.
This corner is located by GPS reference stations "Haeuszer & Hyde AZ"

Corner History:

1854 Gov't Notes, William Yerby; 40.0 set a quarter post in mound of earth & sod. Deposited charcoal and made trench with pits and planted osage orange seed E & W.

10-31-2007 County Surveyor set conc. nail at surface at assumed location. Point falls inline with twp road west and in centerline of T.H. #63.

8-20-2012 Joel Thoreson, Olmsted County Surveyor, visited the the area of the corner and found no survey monuments. Found N-S highway and township road west. The MNDOT Hwy 63 right of way map 33-80_004 shows the following note which references the corner, "Corner at intersection of roads North, South & West, 42.0' right of P.O.S.T. 127.0' ahead of P.I." Contacted the Survey Department at the MNDOT District Office and received a computed centerline alignment and a computed corner location based on said note on the right of way map.

9-5-2012 Olmsted County survey crew set a 4' telspar pipe with cast iron cap at the coordinate position provided by MNDOT.