Certificate of Location of Government Corner

ID#: 830606 **Description:** W 1/4 SEC COR 6 83 **Date Set:** 9/6/2012 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is up 0.3'
The monument falls between N-S fence and RR tie used as fence corner for fence west.
This corner is located by GPS reference stations "Webster C & D"
Sign on post for fence west.

Corner History:

1854 Gov't Notes; 40.0 chs set post for 1/4 section corner. RPs- 14" burr oak S 3 1/2°W 8.0, 20" burr oak N7 1/2°W 487,8.76 14" burr oak.

5-1879 T. Hunter Pg.359 No.350; Found fence corner post averred by adjacent land owners to be where original stake corner stood. 16 west set stake.

6-4-1980 Zenk Engineering set 3/4" pipe with cap #11009 (outside diameter?)

8-6-1984 V. Fangman found and used 5/8" pipe.

9-12-1990 County Surveyor found 1/2" pipe with cap # 11009 between RR tie corner post to fence west and corner post to fence N & S. Also 8"x9" top limestone with top 2" exposed 3 1/2' north of pipe found.

9-21-1990 County Surveyor dug from pipe north 4 1/2' to check stone position from 2' west to 2' east of stone. Found no evidence post hole except for two post E & W of pipe. Nailed sign to south side of RR tie corner post. We dug out stone when stood up it is 0.38' south of position shot. Stone size 9x9x17. RPs- P.K nail inpp# 35294 SW 19.87', CSD in brace post south 10.55', CSD in fence post north 8.45'.

10-14-2005 County survey crew found 1/2" pipe with plastic cap RLS 11009 up 0.2'. Monument falls inbetween 2 fence posts set within 0.8' of one another. Pipe checks with 2 existing ties PP has been replaced.

9-13-2011 County survey crew found 1/2" pipe with cap leaning north. Straightened pipe and verified ties. Probed for stone north of pipe but did not find.

9-6-2012 County survey crew removed 1/2" pipe and replaced it with a 4' telspar pipe with cast iron cap.