Certificate of Location of Government Corner

ID#: 830607 **Description:** NW SEC COR 6 83 **Date Set:** 10/3/2005 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fence south
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Ball; 79.33 intersected 2nd Standard Parallel 942 links east of 1/4 section post on south boundary of section 36 twp 109 north range 14 west & built mound with trench and drove charred stake at center.

1875 State law required monuments to be set at township corners. Thomas Hunter, County Surveyor, placed stone monuments as required.

1878 T. Hunter; Corner gone, found NW corner 1 and SW corner 36 109-14. Measured and set twp corner.

1946 MHD found 8x8x24 limestone with hole in center 4' north of corner post. Book #144.

7-6-1964 County Surveyor found the NW section Corner Section 6 Farmington Township which was evidenced by Engraved township corner stone. Placed a cast iron monument above said stone.

4-25-1995 County Surveyor found C.I.M. with top 2 sections broken off. We dug down to the lower half which is ok. It is still located between two steel posts. There is no linger a fence directly South of the corner. RPs-North to steel fence post 0.6', this corner lies 3' north of the east west fence.

9-27-2005 County Surveyor found broken CIM down 0.4' in good condition.

10-3-2005 County Surveyor removed broken CIM and found engraved twp stone down 1.9' in good condition. Removed 10"x10"x30" engraved stone and set 7' telspar pipe w/cast iron cap up 0.6'. Set post w/sign.