Certificate of Location of Government Corner

ID#: 830804 **Description:** 1/4 SEC COR 8 17 83 **Date Set:** 7/21/2003 **County:** Olmsted

Section: 08 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.4'
The corner falls 2' south of centerline of TH 247 and 105' west of centerline of driveway south
This corner is located by GPS measurement

Corner History:

? Gov't Notes; 40.05 set quarter section post in mound with trench, pits, and charred stake and osage orange seed E & W.

5-1878 Hunter Pg.347 No.340; Corner gone. Mr. Deim avers corner stood in mound & pits when he built fence running south in line & 2 rods to corner post which still stood, set temp point as corner.

5-1895 W.Fraser Pg.630 No.570; Found bottom old corner post. Set stake & stone 50 links north inline of fence running south. 16 south set stake & stone.

1944 Found S. 1/4" Corner Section 8 Farmington Township which was evidenced by Boulder placed a 60D Spike above it. RPs- disc in tele pole NE 38.4, disc in corner fence post 27.5.

7-21-1970 County Surveyor falls in cut, now gone.

5-1975 McGhie & Betts set 5/8" pipe by line & measure from South.

7-16-1984 County Surveyor, 1/2" pipe in place 1' south of centerline TH 247.

7-21-2003 County Surveyor found 1/2" pipe down 0.3' in good condition. Set 1" square pipe w/cap at surface over pipe.

5-26-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-12-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-30-2013 County survey crew found 1" square pipe at surface in good condition. Lowered pipe and cap 0.4' in preparation for 2013 road overlay.