# Certificate of Location of Government Corner

**ID#:** 830805 **Description:** SEC COR 7 8 17 18 83 **Date Set:** 3/26/2002 **County:** Olmsted

**Section:** 08 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls 3' south of centerline of CSAH 12 and 39' west of centerline of TH 63
County Survey Disk in PP #34981 NW 135.6'
Concrete nail in guard post SW 28.70'
County Survey Disk in E side PP 46.67'
This corner is located by GPS measurement

**Corner History:**

5-1854 Gov't Notes William B. Yerby, Deputy Surveyor North between sections 17-18. 80.00 chs. Set a charred section post in a mound for Corner to Sections 7,8,17 & 18. Made trench and pits and planted Osage Orange seed on the N.E. and S.W. sides of the trench.

5-1878 Thomas Hunter (P.347 No. 340), County Surveyor, could not find this corner. Set a stone 4"x12"x12" by the testimony of a local landowner.

6-1879 Hunter (P. 361 No. 352) found stone P. 347.

5-1895 William Fraser (P.630 No. 570), County Surveyor, found stone P. 347.

? Corner now 3/4" rod centerline old US 63. RPs- spike in pp NW 131.17, NE corner gas station office SW 114.15.

7-1970 County Surveyor, corner not preserved in old road. Gas station office only remaining Rp, state shows new centerline east. With pp N very near 131 unmarked, but a spike real low on E side could be same hole.

5-24-1976 County Surveyor dug with the backhoe and found 2 limestones with pottery around 9' deep. One stone was 4"x10" x 14" and the other was 4"x10"x12. Put junk around the stone and drove a 4' piece of pipe (with elbow) along side. The corner is 1.56' South and 1.5' East of a Minn. Hwy. Dept. hub found. RPs-CSD pp# 34981 NW 135.6, concrete nail in guard post SW 28.70,

5-28-1976 County Surveyor set a C.I.M. over a 5/8" x 18" rod as the corner at the road surface.

8-7-1980 County Surveyor found CIM 11" deep after T.H.63 overlay. Set 10" CIM over the CIM in place.

7-16-1984 County Surveyor took reference points before grading.

7-26-1999 County Surveyor found CIM 1" deep in blacktop.

6-6-2001 County Surveyor found CIM down 0.3' in good condition.

6-14-2001 County Surveyor set 1" square pipe w/cap as ref pipe for 2001 overlays. Tied out corner.

3-26-2002 County Surveyor set 1" square pipe w/cap at surface from 2001 overlay tie-outs.

3-12-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.