Certificate of Location of Government Corner

ID#: 830806 **Description:** 1/4 SEC COR 7 8 83 **Date Set:** 6/9/2000 **County:** Olmsted

Section: 08 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe with cap RLS #15809

Reference Ties:

The corner falls 2' west of centerline of TH 63, 11' NE of centerline of residential driveway NW and 5' south of fence west
County Survey Disk in PP #50114 WSW 68.38'
County highway disk in N side 24" Cottonwood WNW 110.74'
Ref pipe SSE 252.94'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes William B. Yerby, Deputy Surveyor North between sections 7 and 8. 40.00 chs. Set a chared quarter section post in mound of earth and sod and made trench and pits and planted Osage Orange seed on East and West sides of trench.

5-1858 H.W. McDougall, Surveyor, (Old Road Book--Road No. 107) surveyed the road between sections 7 and 8.

7-1968 John Kerr, County Surveyor, (Kerr Book 100, page 19) "ran East line from highway notes and for south line took fence line running Eand W as a guide as there has never been a survey recorded since the Gov't survey" for a survey in the S.E. corner of the N.E. 1/4 Sec. 7. Kerr apparently used the T.H. 63 P.I. here as the corner.

M.H.D. assumed this corner (a P.I.) shown in line with fences East and West.

8-15-1980 County Surveyor this corner falls in a cut in T.H. 63. The fence line East is gone near the highway and the fence line West is very crooked near the highway. We found the M.H.D. P.I. iron bent over but the irons at the P.C. and P.T. were in good condition so we reset a 1" square by 15" pipe with cap as the P.I. from the P.C. and the P.T. and as 1/4 Cor. 7-8.

7-26-1999 County Surveyor found 1" square pipe with cap in good condition. set ref pipe and took ties.

6-9-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

3-12-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.