Certificate of Location of Government Corner

ID#: 830905 **Description:** SEC COR 8 9 16 17 83 **Date Set:** 4/23/2003 **County:** Olmsted

Section: 09 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.5'
The corner falls in centerline of TH 247 and in centerline of N-S twp road
Minnesota Highway Disk in NE side PP #40306 SE 84.12'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, William Yerby; 80.0 set charred stake in mound of earth & sod for corner to section 8-9-16-17. Made trench, pits, and planted osage orange seed on NE & SW sides of trench.

5-1898 William Fraser Pg.630 No.570; Couldn't find corner.

4-1925 County Highway Department Bk.44 Pg.5; No detail of corner desc. State monument 60D riser; RPs- disc in pp NE 49.5, disc in pp SW 50.0, disc in 15" ash NW 44.3.

1944 county highway department found the Common Corner Secs. 8,9,16,17, Farmington Township which was evidenced by a Stone Monument. Placed 60D Spike above the Stone.

7-1970 County Surveyor, retieing corner, found large iron pin as corner. RPs- State reference point 4' up in pp# 35081 NE 81.06', State reference point 3 1/2' up on SE side pp# 40306 SE 83.99', 8" round conc. RP monu. With 3" metal cap marked PI SW 88.88', conc monu lies 64' south of present center line, corner 2' ± east of center north and south roads.

10-8-2002 County Surveyor found iron rod in good condition down 0.8'.

4-23-2003 County Surveyor dug out 3/4" x 17" iron and set 1" square pipe w/cap in its place flush with surface of TH 247.

5-26-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-12-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

10-18-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-30-2013 County survey crew found 1" square pipe with cap at surface in good condition. Lowered pipe and cap 0.5' in preparation for 2013 road overlay.