Certificate of Location of Government Corner

ID#: 831005 **Description:** SEC COR 9 10 15 16 83 **Date Set:** 4/23/2003 **County:** Olmsted

Section: 10 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.5'
The corner falls in centerline of TH 247, in centerline of CR 128 north and 1' east of centerline of twp road south
This corner is located by GPS measurement

Corner History:

Gov't Notes: 80.00 set a sec cor post in mound of earth and sod made trench and pits deposited charcoal and planted Osage Orange seed on NE and SW.

6-1878 Hunter unrec, Hunter book P.78 No.43 set boulder 8x12x24 with limestone 3x5x12 below. North 4.37-1/2 288.75' to SW cor church loads then 3.75 to NW cor church lands 4.00 264' deep E & W in sec. 10. Meas north 39.90. Meas west 40.22 to S 1/4 9 then 39.78 to SW 9.

4-6-1925 County Highway Department field BK 44 P.7 and 13 align sta. 490 + 51.5 P.I. delta = 0°24' left from west shows 2 ties fe post NW 53.8 and 15" maple SW 47.1 does not identify type of monu if any. P.13 Topog show centerline public rds N & S.

1944 County Surveyor found the Common Corner Secs, 9, 10, 15, 16 Farmington Township which was evidenced by Hub. Placed a 60D Spike.

1964 county highway department found 1" rod in place. Assumed corner.

1969 J. Kerr found rod in center blacktop. Set property corners.

1969 County Surveyor found large solid iron rod in blacktop.

10-8-2002 County Surveyor did not find spike.

4-23-2003 County Surveyor dug out broken pk nail and found 3/4" x 17" iron below as found by County Surveyor in 1969. Pulled iron and set 1" square pipe w/cap in its place flush with surface of TH 247.

5-26-2006 County Surveyor found 1" square pipe w/cap at surface in good condition.

3-12-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.

4-30-2013 County survey crew found 1" square pipe with cap at surface in good condition. Lowered pipe and cap 0.5' in preparation for 2013 road overlay.