Certificate of Location of Government Corner

ID#: 831204 **Description:** 1/4 SEC COR 12 13 83 **Date Set:** 9/7/1979 **County:** Olmsted

Section: 12 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.7
The corner falls 4' north of centerline of TH 247 and 17' east of centerline of field drive north
Chiseled cross in N end 30" RCP NE 99.08'
Chiseled cross in S end 30" RCP SE 98.23'
Punch mark in E end 18" CMP SW 57.14'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes William B. Yerby, Deputy Surveyor
West on true line between sections 12 and 13. 40.01 chs. Set a quarter section post in mound of earth and sod. Deposited charcoal. Made trench and pits. Planted Osage Orange seed N & S. 80.02 chs. To section corner.

6-1867 H.E. Horton, County Surveyor, (Book A, Page 85, No. 130) possibly used this corner to set the Center 13. He measured east to E. Sec. Cor. 12-13 and west to Sec. Cor. 11-12-13-14 and south to the Center 13. His bearings and measurements indicate that this corner lies north of a straight line between the section corners.

4-1886 Thomas Hunter, County Surveyor, (Book A, Page 406, No. 395) used this corner in a survey of the town of Potsdam. He shows "Boulder stone and stake under" at the corner.

4-1925 County Highway Department (County Highway Department Book 44, Page 9) shows a stone monument 4' North of the straight line between the section corners. Measured 2636' East to E. Sec. Cor. 12-13 and 2640.6 West to a point (not described) at Sec. Cor. 11-12-13-14.

9-7-1979 County Surveyor dug for this corner with the backhoe centered over a point 4' North of a straight line between the section corners and 2636' West of E. Sec. Cor. 12-13 as recorded in County Highway Department Book 44, Page 9. Found a 10"x16" topped by 24" long boulder 5' deep. Removed the boulder and found the old stake beneath. Drove a 3/4"x23" iron through the stake and reset the boulder over it with a piece of Cast Iron Monument on the East side. Set a C.I.M. over a 1/2"x19" iron at the road surface.

5-26-2006 County Surveyor found CIM down 0.7' in good condition.

3-12-2007 County Surveyor found CIM down 0.7' in good condition.

4-30-2013 County Surveyor found CIM in good condition.