Certificate of Location of Government Corner

ID#: 831205 **Description:** SEC COR 11 12 13 14 83 **Date Set:** 4/9/1979 **County:** Olmsted

Section: 12 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.5'
The corner falls 1' west of centerline of CSAH 11 north and 1/2' south of centerline of TH 247
SE corner of house NE 64.52'
County Survey Disk in E side PP #32254 SE 86.04'
NW corner store SW 95.80'
SW corner concrete block garage NW 159.70'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes William B. Yerby, Deputy Surveyor
North between sections 13 and 14. 80.00 chs. Set post in mound corner to sections 11,12, 13 & 14. Deposited charcoal. Made trench and pits. Planted Osage Orange sed E & W.

6-1857 H.E. Horton P.85 used corner. Meas east 39.87, meas south 39.76.

6-1867 H.E. Horton, County Surveyor, (Book A, Page 85, No. 130) used this corner (no description given). He measured east to 1/4 Cor. 12-13 and E. Sec. Cor. 12-13. He also measured south to 1/4 Cor. 13-14.

4-1877
4-1886 Thomas Hunter, County Surveyor, (Book A, Page 406, No. 3935) shows "Stone and iron stake" at this corner in a survey of the town of Potsdam.

9-1894 William Fraser, Deputy County Surveyor, (Book A, Page 552, No. 509) found stone and iron stake as given in Survey on Page 406.

4-1925 County Highway Department (County Highway Department Book 44 Page 8) referenced a point here but gave no description.

8-1962 John Kerr, County Surveyor, (Cert. filed and Kerr Book 85, Page 59) found a 3/4" iron rod in the blacktop pavement at this corner.

10-1966 John Kerr (Kerr Book 93, Page 7) shows an iron at this corner. He used the corner to set 1/4 Cor. 11-14 midway and on line.

8-31-1979 County Surveyor dug with the jackhammer and found a 1" x 17" iron under the blacktop over a 1"x 17-1/2" iron over a 6" x 8" x 14" limestone 2.8' deep. There was a large spike driven in the top of the stone and a piece of cast iron along side.

9-4-1979 County Surveyor set a C.I.M. over the stone found 8-31-1979.

5-26-2006 County Surveyor found CIM down 0.4' in good condition.

3-12-2007 County Surveyor found CIM down 0.5' in good condition.

4-30-2013 County Surveyor found CIM down in good condition.