Certificate of Location of Government Corner

ID#: 831406 **Description:** 1/4 SEC COR 14 15 83 **Date Set:** 7/8/1994 **County:** Olmsted

Section: 14 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' west of centerline of CSAH 11 and in line with fence west
The monument is down 0.8'
Spike in fence post ENE 55.45'
Spike in fence post SW 86.65'
Spike in PP SE 91.15'
County highway disk in PP SE 98.4'
County highway disk in CP E 54'
County Survey Disk in CP W 48.81'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes: William Yerby, 40.00 set a quarter sec post in mound of earth and sod. Deposited charcoal, made trench and pitts, planted Osage Orange seed E and W.

9-1894 W. Fraser P.552 No.509 S.14. K. Lampreaht corner could not be found but Mr. H. Schacht avers he set fence running east on direct line and corner post 33' east of corner stake then standing. Set boulder in line fence east and 33' W of cor post.

5-1900 Ch. Armstrong P.667 No.593 S.15. A. Kruger used corner not mentioned only the center was set at intersection of all right lines.

5-1932 County Highway Department B.67 P.12. Found stone boulder 6x8x15 corner PI delta 0°03' left going south. Sta 26+64.3, meas south 2629.9. Sp in maple SE 45.95, Sp in elm E 33.13, fence post W 28.6, tele P SW 47.3. Corner lines fences east and west.

1951 County Highway Department B.199 P.5 found boulder stone 6x8x15 found. Set 1" drill steel riser. Sp fence post likely ENE 55.45 (gone 83). Sp fence post 1961 ties SW 86.65 (gone 83). Sp power pole SE 91.15. Meas south 2629.3, meas north 2630.6.

6-21-1957 County Surveyor found common 1/4 Corner Secs. 14 and 15, Farmington Township which was evidenced by 6"x8"x15" Limestone and placed a 1" drill rod above the limestone.

6-15-1983 County Surveyor found county highway department drill steel down 3", 1' west of centerline N-S C.R. 11 and in line fences east and west. Set nail at road surface over iron. RP: CSD N side c.p. west 48.81 old county highway department nail NE side (down low) PP #35180 SE 91.18.

7-29-1993 County Surveyor Referenced Corner before milling & resurfacing

7-8-1994 County Surveyor, the Set 1" sq. pipe w/cap as final corner R.P.'s the Corner is 1/2' west of centerline CR #11 and in line of fence west CSD in C.P. West 48.81'.

10-10-2002 County Surveyor found 1" square pipe w/cap in good condition down 0.1'.

5-24-2011 County survey crew found 1" sq. pipe with cap in good condition. Drove pipe down below bituminous in preparation for road surface milling and overlay.