Certificate of Location of Government Corner

ID#: 831606 **Description:** 1/4 SEC COR 16 17 83 **Date Set:** 10/11/1965 **County:** Olmsted

Section: 16 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2' west of centerline of N-S twp road and in line with fences east and west
County highway disk in 8" cedar post E 34.0'
1/2" steel rod in fence line E 50.0'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes: William Yerby, 40.00 set a chared qr sect post in mound of earth and sod. Made trench and pits and planted Osage Orange seed on E and W sides of trench.

5-1878 T. Hunter P.347 No.340 corner came in road on point of a hill which had been cut down several feet and corner destroyed. Settlers aver that fences east and west were set opposite corner when it was standing. Accepted fence lines as northing and southing to set center section. Meas south 39.96 2637.38'

5-1898 W. Fraser P.630 No.570 used assumed corner as in P.347. Meas south 39.90 2633.4' this meas 6 lks shorter than Hunter but from center south the meas was 4 lks shorter so porp nearly same.

10-11-1965 County Surveyor found common quarter corner sections 16 and 17 Farmington Township which was evidenced by Corner gone deep cut in road and placed a permanent Cast Iron Monument over 1/2"x12"rod M&L.

10-10-2002 County Surveyor found CIM in good condition down 1.1'.