Certificate of Location of Government Corner

ID#: 831706 **Description:** 1/4 SEC COR 17 18 83 **Date Set:** 6/9/2000 **County:** Olmsted

Section: 17 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 3' west of centerline of TH 63, in line with fence west and 11' south of centerline of field drive west
NW Corner of corn crib SE 142.6'
County Survey Disk in PP #34965 W 62.82'
Ref pipe W 59.43'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes William Yerby North between sections 17 and 18. 40.00 chs. Set a charred quarter post in mound of Earth and Sod and made trench pits. Planted Osage orange seed on the East and West sides of the trench.

5-1878 Thomas Hunter (P. 347 No. 340), County Surveyor, could not find this corner. Set a 5"x8"x14" stone midway and on line as the corner.

6-1879 T. Hunter (P. 361 No. 352) found stone P. 347

5-1898 William Fraser (P. 630 No. 570), County Surveyor, found stone P. 347.

5-1954 McGhie and Betts found a 5"x8" topped stone down 3.5' in T.H. 63. Set a 1"x3' pipe over the stone.

5-26-1976 County Surveyor dug with the backhoe in T.H. 63. Found a 5"x8"14" stone 9' deep with McGhie's pipe over it. Removed the pipe and put scrap iron around the stone. Set a C.I.M. over a 3/4" rod at the surface of the road.

7-26-1999 County Surveyor found CIM in good condition 5" deep in blacktop. Set 1" square ref pipe and took ties.

6-9-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

3-12-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.