Certificate of Location of Government Corner

ID#: 832005 **Description:** SEC COR 19 20 29 30 83 **Date Set:** 10/13/1965 **County:** Olmsted

Section: 20 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1-1/2' north of centerline of CR 121 and 17' east of centerline of field entrance south
The monument is down 1'
Old County Highway Disc in N side PP #34846 SE 93.30'
Minnesota Highway Disc in N side PP #34846 SE 93.43'
Punch hole in E end CMP NE 30.82'
Flange of channel iron post w/sign S 34.51'
This corner is located by GPS measurement

Corner History:

5-23-1854 William B. Yerby, Deputy Surveyor, measured north 80.00 chains between Sections 29 and 30. Set post in mound of earth and sod, deposited charcoal. Made trench and pitts, planted Osage Orange seed NW and SE.

4-18-1875 Thomas Hunter, County Surveyor, (Book A, Page 268, Survey No. 266), found short stake in center of road in line of fence south. Claimed to be where old stake stood.

1-17-1878 Thomas Hunter, County Surveyor, (Book A, Page 327, Survey No. 321), found stake with stones around it in center of road. Stone falls 50 links (33') north of south road fence and in line of fence south.

5-28-1878 Thomas Hunter, County Surveyor, (Book A, Page 346, Survey No. 339), found stake and stones.

3-25-1879 Thomas Hunter, County Surveyor, (Book A, Page 355, Survey No. 347), found stake and stones.

4-29-1919 Charles Armstrong, County Surveyor, (Book B, Pages 318-319), corner in deep road cut, now near bed rock. Fence south gone.

10-13-1965 John Kerr, County Surveyor, dug and found nothing. Area in a deep road cut. Set Cast Iron Monument over steel rod by measurements and lines run according to previous survey records. RPs - Center E end 12" field culvert NE 31.0', Disc in TP NE 39.5', Disc in PP ESE 93.2', CHD 40d nail in center T.H. 63 E 636.65'.

5-7-1976 County Survey Crew dug on south side of Cast Iron Monument. Found nothing. Very poor conditions.

6-14-1983 County Survey Crew found Cast Iron Monument down 0.7' in good condition. The corner falls 1-1/2' north of centerline of CR 121. RPs - Old CHD Disc in north side PP #34846 SE 93.30', MHD Disc in north side PP #34846 SE 93.43', Punch hole in top E end CMP NE 30.82', Flange of channel iron survey marker sign post S 34.51'.

7-5-2005 County Survey Crew found Cast Iron Monument down 1.1' in good condition and measured its position using GPS.

3-15-2007 County Survey Crew found Cast Iron Monument down 1' in good condition and measured its position using GPS.