Certificate of Location of Government Corner

ID#: 832106 **Description:** 1/4 SEC COR 20 21 83 **Date Set:** 9/14/2010 **County:** Olmsted

Section: 21 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 13' west of centerline of north-south township road (40th Ave NE), 1' south of fence east and 15' north of centerline of field entrance west
The monument is down 0.5'
County Highway Disc in NE side TP SE 62.85'
Hub nailed to SE side 14" Spruce NE 56.6'
This corner is located by GPS measurement

Corner History:

5-21-1854 William B. Yerby, Deputy Surveyor, measured north 40.00 chains between Sections 20 and 21. Set charred stake in mound of earth and sod. Made trench and pits, planted Osage Orange seed on east and west sides of trench.

5-28-1878 Thomas Hunter, County Surveyor, (Book A, Page 346, Survey No. 339), 1/4 post missing and no evidence of where it stood could be found in the ground. Fence west built when original 1/4 post was standing. Set stake in line with fence west, likely centerline road.

5-7-1900 Charles Armstrong, (Book A, Page 666, Survey No. 592), could not find any trace of corner. Set 6"x7"x10" boulder stone midway and on line at 40.01-1/4 chains.

4-29-1919 Charles Armstrong, County Surveyor, (Book B, Pages 318-319), shows stone and iron bar 2617' north of SE Corner Section 20 which doesn't fit with even his own work.

10-13-1965 John Kerr, County Surveyor, dug and found nothing. Set Cast Iron Monument over 5/8"x19" rod with stone, irons & glass by measurement and line of previous surveys. RPs - Hub nailed to SE side 14" Spruce NE 56.6', Disc in NE Side TP with control box SE 62.85'.

9-14-2010 County Survey Crew found Cast Iron Monument down 1.8' leaning slightly west with head broken off. Took local ties and removed. Found 5/8" rod down 3.2' in good condition. Set 6' telspar pipe with cast iron cap at rod location down 0.5' and measured its position using GPS.