Certificate of Location of Government Corner

ID#: 832306 **Description:** 1/4 SEC COR 22 23 83 **Date Set:** 7/8/1994 **County:** Olmsted

Section: 23 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 11, in line with fence west and 2' north of fence east
The monument is down 1'
Ref pipe W 46.00'
This corner is located by GPS measurement

Corner History:

5-17-1854 William B. Yerby, Deputy Surveyor, measured north 40.00 chains between Sections 22 and 23. Set quarter section post in mound of earth and sod, deposited charcoal. Made trench and pits, planted Osage Orange seed east and west.

5-17-1932 County Highway Department, (CHD Book 67, Page 14), P.I. Sta. 79+36.3, found boulder stone and set pipe. RPs - Spike in fence post SE 37.68', Spike in fence post NE 47.1'.

10-15-1946 John Kerr, County Surveyor, (Kerr Field Book 32, Page 29), found monument.

6-21-1957 County Engineer found boulder. Set 1" drill steel over boulder. RPs - Spike in fence post WSW 51.78', Spike in fence post E 51.51', Spike in corner post W 49.5', Hub in fence line W 82.89'.

8-1-1961 County Highway Department, (CHD Book 199, Page 4), P.I. Sta. 319+73.4, found 1" drill steel. RPs - Spike in fence post WSW 51.78', Spike in fence post E 51.51', Spike in corner post W 49.5', Hub in fence line W 82.89'.

7-12-1983 County Survey Crew found 1"x10" drill steel down 0.3' in good condition and removed. Found 1"x34" drill steel down 1' in good conditioin and removed. Found 7/8"x31" bent rebar down 3.5' and removed. Found 8"x12"x12" boulder down 5.5' and removed. Found nothing further. Set 1/2" rerod at surface at stone location. RPs - Nail in leaning corner post W 49.75'.

7-30-1993 County Survey Crew found 1/2" rerod at surface in good condition. Set 1" square pipe w/cap as reference and referenced corner prior to cold recycling bituminous project. Removed 1/2" rerod.

7-8-1994 County Survey Crew set 1" square pipe w/cap at surface at 1993 referenced location. The corner falls in centerline CSAH 11, in line with fence west and 2' north of fence east.

3-12-2007 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.

5-24-2011 County Survey Crew found 1" square pipe w/cap at surface in good condition. Drove pipe down below bituminous prior to road surface milling and overlay.