Certificate of Location of Government Corner

ID#: 832504 **Description:** 1/4 SEC COR 25 36 83 **Date Set:** 1/4/2013 **County:** Olmsted

Section: 25 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.5'
The corner falls 5' south of centerline of E-W twp road and 24' east of centerline of field entrance south

Corner History:

11-1886 T. Hunter Bk. A pg. 416 Corner gone, set a quarry stone as the corner Midway and On Line at 2638.68'.

10-6-1972 County Surveyor found small limestone pieces but not very positive and far from the proper station. Reset the corner as in 1886 at 2635.52'. Set a C.I.M. over a small rod with iron parts from a lawn mower motor.

6-15-1983 County Surveyor found CIM ok down 6", 6-1/2' south centerline E-W road and 10' + east of fence line south. RP's: old nail N side telephone pole SW 47.48', Punch hole top E end field drive culverts SE 24.10'. SW corner of W end north bridge headwall ENE 163.14'.

3-28-2008 County survey crew found CIM down 1.1' in good condition.

10-16-2012 County survey crew found cast iron monument in good condition and removed. Found 1/2" rod directly below and removed that also. Both monuments were removed for culvert replacement.

1-04-2013 County survey crew set 4' telspar pipe with cast iron cap at the previously measured cast iron monument position.