Certificate of Location of Government Corner

ID#: 832806 **Description:** 1/4 SEC COR 28 29 83 **Date Set:** 5/19/2006 **County:** Olmsted

Section: 28 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of north-south township road (40th Ave NE), 20' north of centerline of field entrance west and in line with fence east
The monument is down 0.4'
This corner is located by GPS reference stations "Overton A & B"

Corner History:

5-21-1854 William B. Yerby, Deputy Surveyor, measured north 40.00 chains between Sections 28 and 29. Set quarter section post in mound of earth and sod. Deposited charcoal and made trench with pits. Planted Osage Orange seed east & west.

4-14-1875 Thomas Hunter, County Surveyor, (Book A, Page 268, Survey No. 266), found remains of old stake in center of road in line with fence east. Drove short stake.

10-4-1965 John Kerr, County Surveyor, (Kerr Field Book 90, Page 58), set 120d in line with quarter line fences, 4' east of west edge of traveled road.

8-8-1990 Vince Fangman found 1/2" rod. The corner falls 4' west of centerline north-south road.

6-29-2005 County Survey Crew found 1/2" rod down 0.3' in good condition and removed. Dug with backhoe and found two small stones (2"x5"x5") with stake hole between down 6'. Set 1/2" rod in stake hole. Set reference stations "Overton A & B" and measured their positions using GPS.

5-19-2006 County Survey Crew set 5' telspar pipe w/cast iron cap down 0.4' at stake hole location. The corner falls in centerline of north-south township road, 20' north of centerline of field entrance west and in line with fence east.