Certificate of Location of Government Corner

ID#: 832904 **Description:** 1/4 SEC COR 29 32 83 **Date Set:** 7/7/2005 **County:** Olmsted

Section: 29 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 17' east of CP to fences E-W-NE and in E-W fence
Post w/sign 1' south
This corner is located by GPS reference stations "Banitt B & C"

Corner History:

1854 Gov't Notes, William Yerby; 10.0 enter black oak brush N & S. 25.0 leave brush N & S and enter timber N & S. 27.5 enter praire N & S. 39.95 set a quarter section post. 6" burr oak S10°W 139 links. Made trench.

1875 Hunter Pg.268 No.266; Found stake in mound with trench plain.

3-1-1973 County Surveyor measured to corner. Nothing found or set.

6-29-2005 County Surveyor dug 3'x4'x1' deep hole to bed rock. Conditions poor. Found nothing.

6-30-2005 County Surveyor continued to dig to cover M&L and double the 1/16th west CP. Found nothing. Looked for bearing tree SW, no Oak trees at 139 links.

7-1-2005 County Surveyor continued to dig to cover line of fence from west and double 1/16th west. Found nothing.

7-7-2005 County Surveyor continued to dig to cover T. Hunter's measure from west and 1/4 line from north in line with oldest E-W fence. Found northing. Set 4' telspar pipe w/cast iron cap at surface. Set post w/sign.