Certificate of Location of Government Corner

ID#: 833204 **Description:** S 1/4 SEC COR 32 83 **Date Set:** **County:** Olmsted

Section: 32 **Township:** 108N **Range:** 13W **Monument Description:**

Reference Ties:

6" blazed Elm 1.5' south of W 8.25'
20d nail in root SW corner base of 22" blazed Oak N 14.7'
Rod on east side 14" Oak terminal of main fence from north N 29.7' ±
This corner is located by GPS reference stations "Sawyer A & B"

Corner History:

1853 Gov't Notes, John Ball; 5.0 enter grove bears NW, 38.0 leave grove NE, 40.0 set post for quarter section corner. RPs- 18" burr oak N 80W 144, and dug trench.

3-1898 W.Fraser Pg.620 No.563; Found bottom of old stake from bearing tree. Set marked stake and stone 3x9x20. 16 west, south, east, and center NW 1/4 S5 set stake.

10-1970 County Surveyor set nail at 2626.8' from west , line came 5.65' S of NW 5'. Set long sash weight on bed rock on steep rocky slope, subject to wash from field, made walls of large shellrock. Corner came some 4' west of N-S fence at that point, but line very close to main line fence from hilltop north on farm line. RPs- center 6" blazed elm 1.5' south of west 8.25, 20D in root SW corner base of 22" blazed oak N 14.7', rod on east side 14" oak terminal of main fence from north and random field fence Swly N29.7'±. Corner comes on very steep rock slope north of CR# 14.

11-27-1996 County survey crew found sash weight at surface in good condition

7-18-2003 County survey crew visited area of corner. Found nothing. Recent work of new driveway included extensive rock excavation and has pushed material down hill. The monument could now be down 3' - 5' in material or was destroyed by the driveway construction.

9-7-2011 County survey crew dug to a depth of 3' and found no survey monument. No new monument is set due to the steep, rocky terrain. County survey staff computed a location based on 1976 traverse data (see Traverse Drawing 3-84) The computed Olmsted County HARN 96 coordinates are N=200351.1926 and E=633300.4739.