# Certificate of Location of Government Corner

**ID#:** 833205 **Description:** S SEC COR 31 32 83 **Date Set:** 5/10/2004 **County:** Olmsted

**Section:** 32 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 2' east of fence north, 8 1/2' south of fence west and 236 1/2' north of centerline of CSAH 14
Sign in 11" Poplar 1 1/2' NE
This corner is located by GPS reference stations "Baker A & B"

**Corner History:**

Gov't Notes: By John Ball 10-1854 80.00 Set post and drove charred stake for corner to section 5,6,31&32. Built mound with trench per instructions. Planted SE Osage Orange seed, NE Appleseed.

3-27-1898 W. Fraser Pg. 620 No. 563 Found stake in center of mound with stones on two sides. Set new stake with stone 3"x9"x24" by its side. 16 East set stake and stone M&L 19.90'. 16 South set stake on line at 20.67-1364.22' then 19.97' - 1318.0 to W1/4 5. 16 Center NW1/4 5 set stake at intersection lines (19.95 from above 1/16 east to 1/16 corner on N-S 1/4 line.

1941 County Highway Department Book #129 page 16 shows stone.

5-31-1961 John Kerr Set C.I.M. placed by pipe in place of stake. Corner lies just west of fence by small chicken house. RP-center of county road south S 236.4'.

12-18-1997 County Surveyor found C.I.M. and took a new reference. RP- 8' south of corner post to fence N & W, 1 1/2' south of 8" poplar, sign in 8" poplar.

11-15-2002 County Surveyor found CIM leaning slightly South due to tree and stone pushing CIM towards the face of cut for side slope for home.

5-10-2004 County Surveyor found CIM at surface leaning SSE due to tree root. Removed CIM and found nothing beneath. Set 3 1/2' telspar pipe with Cast Iron Cap at surface at computed position from previous measurements.

10-19-2010 Brian Veronen, MNDOT LSIT, found cast iron cap on telspar pipe in good condition and checked ties.