Certificate of Location of Government Corner

ID#: 833306 **Description:** 1/4 SEC COR 32 33 83 **Date Set:** 5/28/2008 **County:** Olmsted

Section: 33 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of centerline of N-S twp road and 13 1/2' north of fences east and west
This corner is located by GPS reference stations "Ohm D & E"

Corner History:

1854 Gov't Notes, William Yerby; 40.0 set quarter setion post in mound of earth & sod. Deposited charcoal, made trench with pits, and planted osage orange seed E & W. 75.0 small stream 4 links wide course NE.

10-25-1893 W.Fraser Pg.536 No.498; set temp point. M and L between stone at SW 33 and line of fence at NW 33.

9-1965 J.Kerr set 120D in line east-west fences in center road.

11-27-1996 County Surveyor found J.Kerr 120d spike. Set 120d spike in its place 3" deep in N-S rock road. The spike is 2 1/2' west of centerline N-S road & in line of fences E & W.

5-9-2005 County Surveyor found J. Kerr 120d spike in good condition.

5-28-2008 County survey crew found J. Kerr 120d spike down 0.4' in good condition and removed. Set 4' telspar pipe w/Cast Iron Cap down 0.5' at M and L position as per W. Fraser in 1893. From GPS and traverse data.