Certificate of Location of Government Corner

ID#: 833405 **Description:** S SEC COR 33 34 83 **Date Set:** 6/8/2000 **County:** Olmsted

Section: 34 **Township:** 108N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' south of centerline of CSAH 14 and in centerline of N-S twp road
PK nail in NW side PP #38403 SW 63.35'
PK nail in SE side PP #44148 NE 84.5'
PK nail in NE side PP #38404 NW 61.1'
Center NE'ly one large pipe power mast controling switches on PP #44147 SE 76.3'
Ref pipe NW 70.96'
This corner is located by GPS measurement

Corner History:

10-1853 John Ball, 80.00 Set post and drove charred stake for corner to section 3,4, 33&34. Built mound with trench per instructions. Planted SE Osage Orange NE Apple Seed.

10-1893 W. Fraser, P.536, No.498 - Corner gone. Set stone 6x6x18 as corner on town range line and midway 40.02' between S1/4 33 and S1/4 34. Measure north to M&L 39.982/3.

9-1930 Found stone recorded 3' deep measure east 2638.6'

1941 County Highway Department Book #129 Pg.14 - Stone monument 60d nail on top.

8-1966 J. Kerr dug in blacktop road for deep hub. Found hub deep over 4'. Set 4' rod until road settled. Later set CIM over 1/2"x2' rod. Corner lies in 4-way road intersection. Spud on NE side power pole SE 55.8'. Spud on NW side power pole SW 62.8'. Spud likely SE side power pole NE 99.6'. Measure west 2637.88' (1960). Set iron 635.25' for prop corner also 519.75'

10-9-1972 County Surveyor found CIM within 2" a surface seems all power pole references either gone or changed.
76.3' SE to Center NE'ly one large pipe power mast. Controlling massive switches on pole top #44147. 63.35' SW to PK nail on NW side PP 38403. 84.5' NE to PK on SE side PP 44148. 61.1' NW to PK nail on NE side PP 38404. Measure north to CIM over stone found 10-9-72. Then 2637.27' to stone at 27-28-33-34. Making new 1/4 corner .32 west of direct line .73 north of Midway

7-11-1990 County Surveyor found CIM down in blacktop 6" all 1972 ties in place.

8- 1996 Dean Strange of People's Coop found CIM, about .6' deep.

6-14-1999 County Surveyor found CIM 0.6'. Set ref pipe and tied out corner.

6-8-2000 County Surveyor set 1" square pipe w/cap at surface from 1999 tie out.

5-20-2005 County Surveyor found 1" square pipe w/cap at surface in good condition.