Certificate of Location of Government Corner

ID#: 833406 **Description:** 1/4 SEC COR 33 34 83 **Date Set:** 10/9/1972 **County:** Olmsted

Section: 34 **Township:** 108N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2 1/2' east of centerline of N-S twp road
Old spike in NE side Pine NW 54.47'
Spud in S side PP #19909 ESE 27.13'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes William B. Yerby Deputy Surveyor North between section 33 and 34. 40.00 chs. Set a quarter section post in mound of earth and sod. Deposisted charcoal and made trench and pits, planted osage orange seeds east and west.

11-1877 Thomas Hunter County Surveyor (p 324 No. 318) Surveyed in section 34 at 1/4 corner 33-34. Found stone planted in center of road as 1/4 post.

10-1893 William Fraser, Deputy County Surveyor, surveyed in section 33 and 34. At 1/4 33-34 could not find anything, so set stone with stake on top midway and on line between section corners. Corner + or - 8 south of fence running east, also Mr. Walker and Searls claimed that's about where the original 1/4 post stood.

8-15-1960 John Kerr, County Surveyor, (Book 80 p 49) Surveyed in section 34 at 1/4 corner 33-34. Dug and found marks in clay showing imprint of stone, and stake beneath it. Placed a 1/2" x 4' steel rod with 1"x2" stake on north side.

7-1964 John Kerr, County Surveyor, set C.I.M. in place of rod. RPs- 60d in 12" blazed pine NW 51.41', spud pp SE 31.2', cross in north end field entrance culv. E 17.9'.

10-9-1972 Roger Brand, County Surveyor, dug east of Kerrs C.I.M. found 2 limestones, lower stone west of upper stone, used upper stone 3" x 6" x 12", which is 0.3' west of on line and + or - 0.7' north of midway as set by Fraser in 1893. Removed Kerrs C.I.M., set C.I.M. over upper stone as 1/4 corner 33-34. RPs-13.71 4' south of east to punch hole in north end 12" field culv., 27.1 3' south of east to original spid in south side pp# 19909, 54.47' NW to 40d north side 12" pine.

6-14-1983 County Surveyor found C.I.M. down 13" in crushed rock road took ties. RPs-Old spike in NE side of pine tree N.W. 54.47, C.I.M. 2.5' East of centerline of N-S road, Spud in south side of P.P. #19909 ESE 27.13', centerline 50th Avenue N.E..

5-20-2005 County Surveyor found CIM down 1.1' in good condition.