Certificate of Location of Government Corner

ID#: 840106 **Description:** 1/4 SEC COR 1 2 84 **Date Set:** 10/17/2005 **County:** Olmsted

Section: 01 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

120D spike in blazed 24" Burr Oak N 11.6'
Post w/sign 2' west
This corner is located by GPS reference stations "Yanish A & B"

Corner History:

1854 Gov't Notes, M.Karrick; 40.0 set 1/4 section post. RPs- 14" burr oak N55 W150, 14" burr oak N68 E142.

5-1879 T. Hunter, Pg.359 No.350; Corner missing. Mr. N.A. Rosenbloom avers he set his fences north and east from corner and corner post where original corner stood. Meas. North, south, and east.

12-1895 W.Fraser Pg.586 No.534; Found Hunter's point and bearing tree took at that time. 16 south set stake.

1916 Power Dam Survey Found stone.

1930 J.Kerr found stone erect and in good shape.

7-1964 J.Kerr found stone and set CIM with large stone by its side. RPs- 120D in blazed 24" burr oak, green steel fence post S 1.0', 1" pipe up 36" NW 0.6'.

12-14-2000 County Surveyor found CIM up 0.1' leaning slightly south. Green steel fence post laying flat.

10-17-2005 County Surveyor found CIM up 0.1' leaning south packed in stones. Plumbed up CIM and took ties. Removed CIM and found nothing beneath. Set 7' telspar pipe w/cast iron cap at surface at plumb position. Set post w/sign.