Certificate of Location of Government Corner

ID#: 840107 **Description:** N SEC COR 1 2 84 **Date Set:** 7/6/64 **County:** Olmsted

Section: 01 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1 1/2' south of centerline of E-W twp road and 42' east of centerline of farm drive south
County Survey Disk in NE side PP #46748 NW 55.60'
Disc in PP SW 43.03'
Rivet in E end CMP SW 36.45'
Center of 12" Cedar tree SW 39.3'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, M.Karrick; 79.93 Intersect Standard parallel No.2 930 links east of 1/4 section post in south boundary of section 36. RPs- 10" burr oak S54 W129, 10" burr oak S40 E316.

5-1879 T. Hunter Pg.359 No.350; Found stake.

12-1875 T. Hunter BK.4 Pg.82; found stake marked "Road" said to be set by H.Hunter by B.T. in survey of road.

12-1895 W.Fraser Pg.586 No.534; Found limestone set by Hunter Pg.359

1930 J.Kerr found stone and set brick and other junk by stone.

1946 county highway department Bk.144 Pg.75; Found stone. Placed 3/4" rerod by side. RPs- spike in pp WNW 52.04, Co FPS 19.24.

7-6-1964 J. Kerr found limestone 9" x 12" x 28" 3/4" rod broken brick. Set CIM over 1 1/4"x14" pipe. RPs-Northwest disc in power pole 56.6 feet. Southwest disc in power pole East side of farm drive 43.1 feet. Southwest to rivet in East enc of farm entrance culvert 36.45 feet. South Southwest center of 12" cedar tree 39.3 feet. Center of South tree clump of 5 Burr Oaks Southwest 113.5 feet.

12-14-2000 County Surveyor found CIM down 0.9' in good condition

9-26-2005 County Surveyor found CIM down 1' in good condition.