Certificate of Location of Government Corner

ID#: 840108 **Description:** N 1/4 SEC COR 1 84 **Date Set:** 5/16/2006 **County:** Olmsted

Section: 01 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' west of centerline of CR 114 south, 2 1/2' south of centerline twp road east and in centerline of twp road west
County highway disk in TP stub NE 44.69'
County Survey Disk in S side PP #46382 WNW 111.21'
This corner is located by GPS measurement

Corner History:

5-1879 T. Hunter Pg.359 No.350; Set stake on range line. 16 east set stake.

1946 county highway department Bk.144 Pg.75; found limestone. Set 3/4" rod on north side. RPs- disc in 24" maple SW 50.25, spike & disc in pp NW 65.27', disc in pp NW 60.2, spike & Disc in maple SW 74.65'

7-7-1964 County Surveyor found limestone with + 3/4" rod North of stone. RPs-Southwest to drag tooth in 24" maple 68.85 feet. Northwest disc in power pole 42.25 feet. Northeast disc in telephone pole 47.6 feet. Southeast disc in power pole 74.6 feet. Northwest to + punched in North end culvert 23.95 feet. Southwest to + punched in South end culvert 30.47. Feet.

7-20-1990 County Surveyor set C.I.M. over C.I.M. see card for ties. Corner 4 1/2' West of CR 114 running South and CR 80 running North and 2 1/2' South of centerline twp road East and in centerline road West. county highway department disc in telephone pole stub NE 44.77. CSD in telephone pole stub NW 59.32.

7-25-2005 County Surveyor found CIM down 0.3' in good condition.

1-5-2006 County Surveyor found CIM without head down 0.7' in good condition.

5-16-2006 County Surveyor found CIM with head broken down 0.3', took local ties and removed. Found another CIM down 1.2' in good condition, ties matched, removed. Found 3/4" rod down 3.0' along north side of stone, removed rod. Did not uncover stone but did probe stone down 4'. Set 3' telspar pipe w/CIC from local ties taken from first CIM over stone down 0.45'. CSD with concrete nail in south side of PP #46382 WNW 111.21'. county highway department disc in TCM box brace post NE 44.69', stub pole to the NW gone.

5-7-2007 County Surveyor found telspar pipe w/CIC down 0.45' in good condition.

8-25-2011 County survey crew found telspar pipe with cast iron cap in good condition.