Certificate of Location of Government Corner

ID#: 840207 **Description:** N SEC COR 2 3 84 **Date Set:** 9-20-2011 **County:** Olmsted

Section: 02 **Township:** 108N **Range:** 14W **Monument Description:** Computed location in lake

Reference Ties:

Meander Corner East:
The corner falls 8 1/2' N of PP line east
Concrete nail in SW side PP #35423 SE 16.44'
Meander Corner West:
The corner falls 3' west of top bank of Lake Zumbro
Post w/sign and bird house 0.2' east
This corner is located by GPS reference stations "Shangrila A & B"

Corner History:

1854 Gov't Notes, M.Karrick; 80.30 Intersect Standard Parrallel No.2 995 links east of 1/4 section post in south boundary of section 34. RPs- 10" burr oak S43 W147, 14" burr oak S67 E100.

12-1895 W.Fraser Pg.586 No.534; Corner in open field and couldn't be found. Set limestone.

1916 Power Dam Survey found stone.

9-1972 Olmsted County Surveyor, corner used in power dam flowage. Now under lake in main body of lake. 16 east iron found, 16 west CIM set.

8-1990 Olmsted County Surveyor, corner set at intersection line from 2-3-10-11 over 1/4 2-3 and line from N 1-2 over N 1/4 2.

10-12-2005 1/16th East: Olmsted County survey crew found drag tooth laying flat. PP tie and Oak tree ties in place. Fence post west gone. Removed drag tooth.

Meander Corner East: Olmsted County survey crew found 1/2" pipe at surface

Meander Corner West: Olmsted County survey crew found CIM up 0.1' in good condition.

10-13-2005 1/16th West: Olmsted County survey crew visited area of corner and found nothing. Newer fence inplace destroyed corner.

9-20-2011 Olmsted County Surveyor computed a coordinate location of the corner by using a line from section corner 2-3-10-11 over the quarter section corner 2-3 and line from meander corner west to south section corner 34-35, Township 109, Range 14. Computed a Olmsted County HARN 96 coordinate of North=231805.9693 and East=614957.5669.