Certificate of Location of Government Corner

ID#: 840305 **Description:** SEC COR 3 4 9 10 84 **Date Set:** 6/16/2004 **County:** Olmsted

Section: 03 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 3 1/2' east of centerline of N-S twp road and in centerline of twp road west
Center of No. plate in W side PP #37761 SSE 99.7'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, M.Karrick; 80.0 set corner post to section 3-4-9-10. RPs- 10" aspen S18 W190, 8" aspen N 81 W195.

6-1891 T. Fraser unrecorded survey found the boulder set by Hunter earlier.

10-1892 T. Fraser Bk. A pg. 481 found the boulder and set the 1/16th North.

6-1902 W. Fraser Bk. B pg. 42 found the boulder and set an iron as the 1/16th corner E. He also set a stone at the 1/16th South.

9-1936 J. Kerr Bk. 11 pg. 75 found the 1/16th iron E. & 1/16th stone West.

8-9-1972 County Surveyor found the boulder and the 1/16th iron E., and the 1/16th stones West and South.

8-18-1972 County Surveyor found boulder 11x14x16 and stake. Set steel fence post with CIM on top .05 south and .14 east to make 1/16 stone west 1318.5. Corner very near center road N & S. RPs- 99.7 SSE to center number plate W side pp #37761.

4-11-1983 County Surveyor found CIM in good condition.

6-15-2004 County Surveyor found CIM with head broken off down 1.0' in good condition.

6-16-2004 County Surveyor took local ties and removed CIM and fence post. Set 4.0' telspar pipe with CIC down 0.5'.