Certificate of Location of Government Corner

ID#: 840306 **Description:** 1/4 SEC COR 3 4 84 **Date Set:** 6/16/2004 **County:** Olmsted

Section: 03 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 13' NE of centerline of twp road on curve, 2' south of fence west and 18' south of centerline of driveway east
Pop cap in PP #37777 SE 45.00'
This corner is located by GPS measuement

Corner History:

1854 Gov't Notes, M.Karrick; 40.0 set 1/4 section post in mound with trench and pits, charred stake, and osage orange seeds NE & SW.

6-1891 T.Fraser unrecorded Pg.95; Found stake claimed to be original corner location.

10-1892 T.Fraser Pg.481 No.458; Road layout same as above no meas, no desc. All corners, but SW corner 3 likely stakes.

5-22-1934 J.Kerr Bk.3 Pg.46; Found stone at E 1/4 3. Set center 3 at 2638.2 then 2649.8 west of center to W 1/4 3. Found stone set by Rucker avered by Mrs. Rucker set on stake. RPs- Corner post east 19.5', cross in culv. Headwall SW 15.5.

5-20-1969 County Surveyor found boulder stone as recorded. Set CIM over stone with 1 1/4"x4' conduit 2" below top of CIM. RPs- orangeade cap in pp# 37777 SE 45.00, nail in hub on NW side 24" cottonwood, 16" twin oak South SW 36.93, bottle cap on top corner post fences E & S E 25.65.

4-11-1983 County Surveyor found C.I.M. on N.E. edge of road on curve from South to N.W. corner in line with fence East and 2' South of line of fence West. Checked R.P.'s: Pop cap in P.P. # 37777 S.E. 45.00. Bottle cap in top of corner post (leaning East) E. 25.65. Kerr's irons East and West in are either buried or gone did not try to dig them up. Hub gone on cottonwood S.W.

6-16-2004 County Surveyor found CIM down 1.1' leaning SE. Took tie to PP #37777 and found a 0.07' difference. Took local ties and removed. Set 4.0' cast iron cap on telspar pipe down 0.8' from the pp tie and local ties.