Certificate of Location of Government Corner

ID#: 840308 **Description:** N 1/4 SEC COR 3 84 **Date Set:** 9/22/72 **County:** Olmsted

Section: 03 **Township:** 108N **Range:** 14W **Monument Description:** Meander Corner South: Cast Iron Monument 270' south of true 1/4 corner
Meander Corner East: Cast Iron Monument
Meander Corner West: Cast Iron Monument

Reference Ties:

Meander Corner South:
The corner falls 30' S of lake shore
Punch hole in N end 15" CMP ESE 14.3'
60d nail in N side 36" Oak up 15" ENE 25.57'
Corner of house siding on SW corner of house SSE 60.15'
Post w/sign 1/2' north
This corner is located by GPS reference stations "Trost A & B"
Meander Corner East:
The corner falls in line with fence east and 1 1/2' east of top bank of Lake Zumbro.
Post w/sign 1' west
This corner is located by GPS measurement
Meander Corner West:
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

5-1892 T. Fraser Bk. A pg. 481. Set the 1/16th corner between the center 3 and the N. 1/4 corner 3. He also staked the road between them.

12-1895 W. Fraser Bk. A pg. 586. Ran the line from N.W. 3 to N.E. Cor. Sec. 1 Meas. N line 3 at 80.15 ch. And the N line of 2 at 79.35 ch.

9-22-1972 County Surveyor. Set the (Meander corner) to the N 1/4 corner.

4-11-1983 County Surveyor found Cast Iron Monument Meander corner ok. Put survey marker sign post .45 North and steel fence post .8 South of said monument.

6-17-2004 Meander Corner South: County Surveyor found CIM down 0.1' in good condition.

10-12-2005 Meander Corner East: County Surveyor found CIM at surface in good condition. Set post w/sign.

10-17-2005 Meander Corner West: County Surveyor found CIM down 0.2' in good condition. Set post w/sign.