Certificate of Location of Government Corner

ID#: 840404 **Description:** 1/4 SEC COR 4 9 84 **Date Set:** 8/16/2005 **County:** Olmsted

Section: 04 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6 1/2' south of centerline of E-W twp road and in line with fence south
County Survey Disk in old CP SW 17.52'
County Survey Disk in W side PP SE 33.55'
County Survey Disk in W side PP NE 35.98'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes, M.Karrick; 40.0 set temp 1/4 section post west on true line between section 4 & 9. 40.0 set.

6-1891 T. Fraser unrecorded survey in an old field book. Found a large boulder with a wood stake below stone. Reset an 8" by 12" by 32" boulder above a stake. Meas. West 2633.5' and Meas. East 2639.0' near direct line.

8-9-1972 County Surveyor found a large boulder. The recorded stone at the 1/4 corner. Set a C.I.M. over 2' iron rod and glass .4' east of iron placing corner over stone. RPs-, 7.5 N to center E-W road, 18.55 5' east of south to CSD on east side corner post .45 south direct line.

4-11-1983 County Surveyor found CIM in good condition.

8-16-2005 County survey crew found CIM down 0.4' leaning to the south. Took ties and removed. Found iron rod down 2.2' in good condition. Tied out and removed. Set 4.0' cast iron cap on telspar pipe down 0.5' at iron location.

5-18-2011 County survey crew found cast iron cap on telspar pipe down 0.1' in good condition. Lowered monument to be down 0.4'.