Certificate of Location of Government Corner

ID#: 840405 **Description:** SEC COR 4 5 8 9 84 **Date Set:** 10/2/2002 **County:** Olmsted

Section: 04 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.3'
The corner falls in E-W fence
Post w/sign 2' South
This corner is located by GPS reference stations "T-Box A & B"

Corner History:

1854 Gov't notes, M.Karrick; Set section post to section 4-5-8-9. RPs- 9" burr oak S8 W265, 12" jack oak N22 W230, 9" jack oak N67 E 225, 7" burr oak S49 E330.

6-1891 T.Fraser Pg,95 unrecorded; at SW corner 4 stone was pulled up and standing at fence corner. Mr.Rice identified corner stone positively as on set 25yrs ago. Found SW b tree remains which set corner. Found butts of enough fence posts east to identify fence. Set stone in proper place. 4x4x30.

5-1892 T.Fraser Pg.485 No.462; Found stone set in previous survye from B tree and testimony of settlers present at that time.

1894 W.Fraser Pg.550 No.508; Found corner . 16 west set boulder stone, 16 center SE 1/4 5 set boulder.

1930 county highway department book #56 page 2, shows stone as corner.

4-23-1969 J. Kerr found limestone at fence corner as recorded. Set CIM over stone flush with surface and broke glass on top of stone. RPs- 4" sq tele cable post bolted to tele pole just south of cable post, west side post to center CIM west .45', 6' steel fence post up 30" north .45'.

10-2-2002 County Surveyor found 21" CIM leaning SE. Removed CIM, found limestone boulder down 2.0'. Took local ties to point on stone, removed stone, set 5' telspar with CIC up 0.2'. Point falls in line with fence running E-W. Set sign & post 2' South of corner.

11-8-2011 Mike Hendrickson, MNDOT Crew Chief, found cast iron cap on telspar pipe in good condition. Set 2 reference ties as follows: Nail and blue disc in east side of fence post, up 1', North, 6.55'. Nail and blue disk in southwest side of 24" burr oak tree, up 2', Southeast, 12.5'.