Certificate of Location of Government Corner

ID#: 840604 **Description:** 1/4 SEC COR 6 7 84 **Date Set:** 7/1/64 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 10' W of N-S elk farm fence
CN & D in NW side 6" Pine up 0.2 SSW 94.36'
CN & D in NW side 6" Pine up 0.2' SW 76.75'
CN & D in NW side 6" Pine up 0.2' SW 98.56'
Post w/sign 10' East
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: M.G. Karrick, Deputy Surveyor N89°43'E on true line between sections 6 & 7. 38.45 set 1/4 section post in mound with trench and pits and charred stake and planted Osage Orange seeds N.E. and S.W.
5-1877 Thomas Hunter (Book A P. 309 No. 303), County Surveyor, found stakes at the 1/16th West and the 1/16th South by H.E. Horton, former County Surveyor.

5-1892 Thomas Fraser (Book A P. 485 No. 462), County Surveyor, found the stake set by H. Horton. He set a stone in its place marked with cross. He measured East to Sec. Cor. 5-6-7-8 and overran Gov't measure by 17 1/2 links (2651.55).

9-1893 William Fraser (Book A P. 485 No. 462) found a boulder stone in the center of the old Gov't mound beside the corner of the fence. Left as found. He set a boulder stone at the 1/16th West on line and at proportionate Gov't measure to W. Sec. Cor. 6-7 (38.61 chs.).

6-1894 William Fraser (Book A P. 550 No. 508) used the corner to set the center 6.

1952 John Kerr (Kerr Book 55 P. 11) found boulder over limestone 3' West of fence corner.

7-1-1964 John Kerr (certificate filed) found a boulder and limestone. Set a C.I.M. over a 1 1/2" x 18" pipe. RPs- 3/8"x4' rod up 2.0' south 0.5', hub on corner post east 2.4'.

9-27-1977 Mn/Dot found Kerr's C.I.M. and took references. RPs-CN & D in 6" pine up 0.2 on N.W. side 94.36. CN & D in 6" pine up 0.2' on NW side 76.75. CN & D in 6" pine up 0.2' on NW side 98.56. C.I.M., steel post NNE 13.6, steel post SSE 16.9.

10-1977 County Surveyor found Kerr's C.I.M. in an extensive survey in this area. Measured 2651.13 East to Sec. Cor. 5-6-7-8 and 2542.67 West to W. Sec. Cor. 6-7.

10-1-2002 County Surveyor found CIM down 0.5' in good condition. Set sign and post 10' East of CIM and outside of 8' fence. Point falls inside of elk fence.

1-27-2003 Mn/DOT Survey Crew found monument in good condition.

2-26-2010 Rudy Martin, MN/DOT Crew Chief, found CIM in good condition.