Certificate of Location of Government Corner

ID#: 840607 **Description:** NW SEC COR 6 84 **Date Set:** 9/22/2009 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The cast iron monument is down 0.5'
The corner falls in centerline of E-W twp road and 265' West of centerline of NW-SE twp road
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes John Ball, Deputy Surveyor 80.93 chs. Intersect 2nd Standard Parallel 11 chs. And 19 lks. East of the quarter section corner on the South line of section 36 township 109N range 15W of the 5th principal meridian. Set post and built mound with trench as per instructions at center drove charred stake.

1875 State law required township monuments be placed at township corner. Thomas Hunter, County Surveyor placed stone monuments as required although there is no survey notes of this particular corner being set.

9-1893 William Fraser (P. 533 No. 496), County Surveyor, found the engraved township monument in the center of the road.

6-1902 Charles Armstrong (P. 54 Book B), County Surveyor, found stone monument in the South wheel track.

6-1902 C. Armstrong (P. 56 Book B) found the township monument.

7-4-1969 John Kerr, County Surveyor, dug and found the township corner in the center of the East-West township road.

7-24-1969 John Kerr took reference points

5-13-1975 Roger Brand, County Surveyor dug down to verify the township monument and found two 10" CIM's over the engraved township monument. Removed 10" CIM's and reset 20" CIM over the stone.

7-7-2001 County survey crew found CIM w/cap broken off down 0.7'. Corner falls in centerline of 520th St and 265' W of intersection of 520th St and Ash Rd NW.

10-3-2002 County survey crew found CIM without head down 0.8' in good condition.

2-15-2006 County survey crew found CIM without head down 0.8' in good condition. Removed CIM and found 10"x10" topped boulder down 2.1' in good condition. Set drill hole in boulder and set 1/2" rerods on N-S-E-W sides of boulder.

7-10-2009 County Surveyor found stone w/drill hole and w/4 irons on each side down 2.5' in good condition. Set CIM over stone.

9-22-2009 Joel Thoreson, County Surveyor computed a new corner location on the standard parallel by intersecting the east line of section 1-108-15 with the south line of section 36-109-15. County survey crew set a cast iron monument at the new corner location which is 0.56' south of the existing CIM over stone. Removed the existing CIM but left the stone inplace.

2-26-2010 Rudy Martin, MN/DOT Crew Chief, found CIM in good condition.