Certificate of Location of Government Corner

ID#: 840608 **Description:** N 1/4 SEC COR 6 84 **Date Set:** 10/20/2009 **County:** Olmsted

Section: 06 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' north of E-W fence and 1 1/2' east of fence south
The monument is up 0.1'
Post w/sign 3' south
This corner is located by GPS measurement

Corner History:

9-1893 W.Fraser Pg.533 No.496 S6; Found nothing of this corner. Relocated corner on town line and gov't proportioned measurement. Set stone 3x6x16 with stake by its side.

6-1894 W.Fraser Pg.550 No.508 S5 & 6; Found corner stone.

6-10-1969 J. Kerr found corner NW 6 and NE 5. Set 1/2" rod 16" deep with glass on range line.

12-3-2002 Olmsted County Survey Crew found 1/2" rod down 1.5' in good condition.

8-23-2005 Olmsted County Survey Crew found 1/2" iron rod down 1.5'. Took local ties and set a Cast Iron Cap on telspar pipe over the 1/2" rod.

10-20-2009 Joel Thoreson, Olmsted County Surveyor, computed a new corner location on the standard parallel by intersecting the N-S quarter line of section 6-108-14 with the south line of section 31-109-14. Olmsted County Survey Crew set a Cast Iron Cap on telspar pipe at the new corner location which is 2.67' south of the existing Cast Iron Cap on telspar pipe. Removed the existing cast iron cap and telspar pipe.

5-6-2010 Olmsted County survey crew found CIC on Telspar pipe up 0.1' in good condition.

2-26-2010 Rudy Martin, MN/DOT Crew Chief, found CIC on Telspar pipe in good condition.