Certificate of Location of Government Corner

ID#: 840706 **Description:** W 1/4 SEC COR 7 84 **Date Set:** 7/1/64 **County:** Olmsted

Section: 07 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 87' west of centerline of twp road
North edge grader blade W 0.9'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor North between sections 7 and 12. 40.00 chs. Set quarter section post. Burr Oak 10 in.S8°E 280 lks. Burr Oak 8 in. S45°W 83 lks.

5-1877 Thomas Hunter (Book A P. 309 No. 303), County Surveyor, states that the corner was gone. He reset a stake from both bearing trees standing. He set the 1/16th North midway (19.94 1/2 chs.) and on line.

5-1891 Thomas Fraser (Book A P. 451 No. 435), County Surveyor, found a stake and stone as set by Hunter. Tested by remains of witness trees and found correct. He measured South 1 1/2 miles to set W. Sec. Cor. 7-18 and the W. 1/4 Cor. 18. His measure South to W. Sec. Cor. 7-18 was 39.66 chs.

5-1898 William Fraser (Book A P. 629 No. 569), County Surveyor, found the S.W. Bearing tree standing and the stump of the S.E. with marks plain and found the old stake which corresponded with the U.S. field notes from the bearing trees. He set a new stake in place of the old stake with three stones around it. He set the 1/16th West midway (1316.04) and on line to the center 12 (a stake and stone set at intersecting 1/4 lines).

5-1917 John Kerr (Kerr Book -10 P. 6), County Surveyor, records a stone at this corner and measure 5159.8 East to the E. 1/4 Cor. 7.

1941 John Kerr (Kerr Book 24 P. 59) states: "Corner is F.P. (fence post) set in concrete. F.P. replaced with grader blade." R.P.: Blaze in 18" Burr Oak S43°W 55.6'. Center of 10" Burr Oak S.E. 21.9'.

6-1960 John Kerr (Kerr Book 81 P. 23) found corner. Measured West 2632.6 to center 12 (found).

7-1964 John Kerr (certificate filed) removed grader blade and set C.I.M. RPs- drag tooth NW side 24" burr oak S43°W 56.52, center 16" burr oak SE 21.9, disc in hub on tlel pole N 113.0, grader blade up 1.8' W 1.0, steel fence post E 1.2.

9-27-1977 Mn/Dot found the C.I.M. and took references. RPs-CN & D (up 1.0) on East side 12" Bur Oak 21.65. CN & D (up 1.0) on SE side 20" Box Elder 12.90. North edge grade blade West 0.9'. C.I.M.

10-1977 County Surveyor found Kerr's C.I.M. during extensive survey in this area. Measured 2630.01 North to the N.W. Cor. 7, 2614.84 South to the S.W. Cor. 7, and 5162.20 to the E. 1/4 Cor. 7.

8-1998 Mn/DOT Survey Crew found monument in good condition.

6-12-2001 County Surveyor found CIM down 0.1' in good condition.

3-1-2010 Rudy Martin, MN/DOT Crew Chief, found CIM in good condition.

11-8-2011 Mike Hendrickson, MNDOT Crew Chief, found CIM in good condition. Set 2 additional reference ties as follows: Nail and blue disk in south side of power pole, up 2', North, 264.08'. Nail and blue disk in west side of power pole, up 2', East, 73.44'.