Certificate of Location of Government Corner

ID#: 840904 **Description:** 1/4 SEC COR 9 16 84 **Date Set:** 4/6/77 **County:** Olmsted

Section: 09 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 4' south of centerline of CR 118, 5' west of fence south and 8' west of fence north
+ in top S end CMP WSW 52.49'
Pop cap in S side PP #37899 SW 93.17'
+ in top N end CMP WNW 53.82'
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: M.G. Karrick, Deputy Surveyor West on true line between sections 9 and 16. 40.00 chs. Set quarter section post in mound with trench and pits and charred stake and planted Osage Orange seeds N.E. and S.W. 80.00 chs. Section corner.

1916 Power Dam Survey (sheet 3060) shows a stone in place at the corner. Measured 2582.1' East to Sec. Cor. 9-10-15-16 and 2684.7' West to Sec. Cor. 8-9-16-17.

5-27-1969 John Kerr, County Surveyor, set a 1/2" x 11" rod midway and on line at 2630.35 between the section corners. The corner came approx. 53' West of the fences North and South. RPs- cross in south end 30" culv 1' west of south 4.5', cross in north end 30" culv near north 21.35' disc in pp# 37899 SW 47.2'.

4-6-1977 County Surveyor dug in line with the fences North and South for the stone recorded by the Power Dam Survey. Found a stake 9' deep with stones on the East and West sides and a stone over it. Drove a 4 1/2' pipe in the stake hole. Set a C.I.M. at the surface of the road over the pipe. The corner is approx. 50.5' East and 4' North of Kerr's iron (removed). The corner is 4' West of the fence South and 7' West of the fence North. RPs- pop cap south side pp# 37899 SW 93.17, cross top south end CMP WSW 52.49, cross top north end CMP WNW 53.82.

Correction of a corner: The correct corner is approx. 50.5' East and 4' North of Kerr's corner (removed).

9-26-2005 County Surveyor found CIM down 0.9' in good condition.