Certificate of Location of Government Corner

ID#: 841004 **Description:** 1/4 SEC COR 10 15 84 **Date Set:** 9/20/2004 **County:** Olmsted

Section: 10 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 7' north of centerline of CR 118 and 2' east of fences north and south
County Survey Disk in E side PP #24377 S 39.63'
Nail & disc in top gate post SW 61.20'
+ punched in cattle pass N 6.88'
This corner is located by GPS reference stations "Tiedman A & B"

Corner History:

1854 Gov't notes, M.Karrick; 40.0 set temp 1/4 section post west on true line between sections 10 & 15. 40.0 set 1/4 section post in mound with trench, pits, charred stake and osage orange seeds NE & SW.

5-1892 T.Fraser Pg.484 No.461 S 10; Found stake with small stones.

? T. Fraser field book 8 p22 says he set stone 18x7 triangle shaped boulder.

6-1902 W.Fraser Pg.42B; Found stone as corner.

1941 J.Kerr Bk.23 Pg.4; Power Dam notes; Set 3/4" pipe with small stones around it. Corner 2' east of N-S fences and 2' from north should road.

5-27-1969 J. Kerr set short CIM over 1/2"x12 1/2" rod on east side of cattle pass. RPs-cross end culv. Pass 6.85', cross south end culv. Pass 21.55, bottle cap driven into top gate post SW 61.2, bottle cap in huge pp# 37867 south 39.0

1-1976 County Surveyor set railroad spike from references.

6-15-2004 County Surveyor found nothing.

9-20-2004 County Surveyor set 1" square pipe w/cap down 0.4' from GPS and traverse data.