Certificate of Location of Government Corner

ID#: 841005 **Description:** SEC COR 9 10 15 16 84 **Date Set:** 6/15/2004 **County:** Olmsted

Section: 10 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 5' south of centerline of CR 118 and 4' east of centerline of twp road south
Nail & disc in PP SW 43.14'
Nail & disc in TP NW 54.70'
1/2" pipe at fence corner up 1' N 33.28'
Nail & disc in PP SE 37.60'
This corner is located by GPS measurement

Corner History:

1854 Gov't notes, M.Karrick; 80.0 set section post to sections 9-10-15-16. Erected mound with trench, pits, charred stake, and osage orange seeds at each angle.

6-1902 W.Fraser Pg.42B S 10; Found stone corner, no other records.

1916 Power Dam Survey shows stone.

5-1941 J.Kerr Bk.23A Pg.4; Found red boulder with cross on top. Set 1/2" pipe riser and junk. RPs- 1/2" pipe in fence line N 33.0, spike in corner post SW 29.75, spike in corner post SE 24.75.

5-20-1969 J. Kerr found boulder stone with + as recorded. Set CIM over stone and iron riser with 1/2"x10" pipe below with glass. PRs-Southwest nail and disc in power pole 43.15 feet. Northwest to nail and disc in telephone pole 54.70 feet. North to 1/2" pipe at fence corner 33.2 feet. Southeast to nail and disc in power pole 30.30 feet.

6-15-2004 County Surveyor found 60d spike down 0.9'. Took local ties and removed. Found CIM down 1.7' in good condition and matching ties to spike. Removed CIM. Set 5' cast iron cap on telspar pipe down 0.5' from local ties.