Certificate of Location of Government Corner

ID#: 841006 **Description:** 1/4 SEC COR 9 10 84 **Date Set:** 3/25/2002 **County:** Olmsted

Section: 10 **Township:** 108N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2' north of centerline of CSAH 12 and in centerline of CR 127
County Survey Disk in W side PP #40418 NE 84.25'
County Survey Disk in E side PP #43049 SSE 81.19'
Top center 5" square tele box NW 89.73'
County Survey Disk in SW side PP #40419 SE 163.72'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: M.Karrick; 40.0 set 1/4 section post in mound with trench, pits, charred stake, and osage orange seeds NE SW.

6-1902 W. Fraser Pg.42B; Found stone as corner, no other records. 16 north set stone, 16 east set stone, 16 center NW 1/4 10 set iron stake, and 1/16 corners north & center NW 1/4 set in 4-1904.

? county highway department Set iron pipe. RPs- hub near elm 72.1', disc in fence post NE 92.0', hub NW 88.4'

9-1939 county highway department Bk.113 Pg.77; Found old survey stake about 3' below surface over iron rod.

5-1969 J. Kerr; Found stub old fence post NE 92.0'. RPs-bottle cap pp# 40418 NW 44.4, bottle cap pp# 37746 NE 48.9, bottle cap pp SW 63.3'. Set CIM over 1 1/4"x14" pipe last 8" solid new blacktop material. RPs-bottle cap in pp# 40418 NW 44.4, bottle cap in pp# 37746 NE 48.9, bottle cap in pp SW 63.3.

5-1975 County Surveyor removed CIM and found 1"x2" hub and 5/8" square rod 3 1/2' deep. Rod bent over. Used bottom as corner location and referenced since road to be changed. Correct corner lies 1.6'N and 2.45' W of Kerr's loction, 1.6'N centerline E-W road, 1'W centerline road N, and 3'W fence line south. RPs- CSD west side pp# 43049 SSE 81.19', top center 5" square telephone box NW 89,73'.

5-1985 County Surveyor found 1" sq. pipe/cap which fit rps NE and SE taken in 1975.

6-6-2001 County Surveyor found 1" square pipe w/cap down 0.2' in good condition.

6-19-2001 County Surveyor set 1" square pipe w/cap as ref pipe for 2001 overlays. Tied out corner and removed 1" square pipe w/cap.

3-25-2002 County Surveyor set 1" square pipe w/cap at surface from ties taken from ref pipe.

6-15-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.