Certificate of Location of Government Corner

ID#: 841306 **Description:** 1/4 SEC COR 13 14 84 **Date Set:** 5/27/77 **County:** Olmsted

Section: 13 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' south of E-W fence and in line with east edge of driveway north
Post w/sign 1' south
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: M.G. Karrick, Deputy Surveyor North between sections 13 and 14. 40.00 chs. Set quarter section post. Bur Oak 10 in. S80°W 165 lks. Bur Oak 7 in. N10°E 185 lks.

1916 The Power Dam surveyors (sheet 3058) assumed a point midway and on line between the section corners as the corner.

8-1929 John Kerr (B.2 P.14), County Surveyor, used a point midway and on line to set the center 14.

5-27-1977 County Surveyor set CIC/square pipe. Corner is 1.5' south of E-W fence and in line with east edge of driveway. Corner 1.4 south and 1.2 west of a 3/8" rod in the E-W fence line. RPs- spike & Disc south side 6" cedar W 20.15, spike & Disc east side blazed elm N4.68.

8-17-1993 County Surveyor found CIC p2 in good condition . Set sign & post ± 1' south of corner.

10-11-2005 County Surveyor found cast iron cap on telspar pipe in good condition down 0.2'.