Certificate of Location of Government Corner

ID#: 841505 **Description:** SEC COR 15 16 21 22 84 **Date Set:** 12/6/2002 **County:** Olmsted

Section: 15 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 100' south of river and 50' north of sharp bank south
Post w/sign 2' North
This corner is located by GPS reference stations "M.K. A & B"

Corner History:

1854 Gov't Notes: M.G. Karrick, Deputy Surveyor North between sections 21 and 22. 80.00 chs. Set post for corner. Burr Oak 12 in. S28W 146 lks. Elm 12 in. N14W 200 lks. Linden 8 in. S67E 120 lks.

11-1872 Thomas Hunter, County Surveyor, found corner standing in mound. N.W. bearing tree standing and other bearing trees were stumps. 18 in. Elm N16W 194 lks.

11-1894 William Fraser (P. 555 No. 512), County Surveyor, found stake and tested stump of N.W. bearing tree which the only remaining evidence. Drove an iron stake and took a bearing tree. 12 in. Elm N36E 7 1/2 lks.

1913 D. Williams (Book B. P. 215), County Surveyor, found iron stake.

6-15-1974 County Surveyor found 1 1/2" pipe down 8". Drove the pipe down and set a C.I.M. and lots of junk around it. Drove 1/2" pipes in all 4 directions (up 6"). Fraser's bearing tree still standing. RPs- ±100' south of river & ±50' north of sharp bank south, 18.0' 60d in Boxelder
Will Fraser's bearing tree N36°E 5'.

An analysis of the above historic recornd indicates that the C.I.M. is a perpetuation of the Original Public Land Survey.

12-6-2002 County Surveyor found CIM busted and leaning down 0.3'. Removed CIM and found 1 1/2" pipe down 1.2' in good condition. Removed 1 1/2" pipe and set 6' Telspar Pipe w/Cast Iron Cap down 0.1'.

7-21-2004 County Surveyor found cast iron cap on telspar pipe at surface in good condition.