Certificate of Location of Government Corner

ID#: 841506 **Description:** 1/4 SEC COR 15 16 84 **Date Set:** 6/24/2004 **County:** Olmsted

Section: 15 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls on the west side of CP to fences S-E
Post with sign 2' south
This corner is located by GPS measurement

Corner History:

6-1854 Gov't Notes: M.G. Karrick, Deputy Surveyor North between sections 15 and 16. 40.00 chs. Set quarter section post in mound with trench and pits and charred stake and planted Osage Orange seeds N.E. and S.W.

1916 Power Dam Survey (Sheet 3060) shows no corner found. Assumed a midway and on line location.

10-28-1971 County Surveyor used the corner post as the corner to stake the road from section corner 9-10-15-16 to the 1/16th South.

3-24-1977 County Surveyor dug around the corner post but did not find anything. Set a C.I.M. over a 1/2" x 2' rod as the corner on the West side of the corner post to fences South and East. RPs-C.I.M. C.S.D. in P.P. # 37948 W.N.W. 24.18.

6-22-2004 County Surveyor found CIM down 0.2' leaning. Need to talk to farmer about grubbing brush so corner can be GPS'd. Power pole gone and corner post pulled out and lying next to fences.

6-24-2004 County Surveyor found CIM down 0.2' leaning east. Took local ties and removed. Found 1/2" iron rod down 2.0' in good condition. Set 6' cast iron cap on telspar pipe up 0.3' at iron rod location.