Certificate of Location of Government Corner

ID#: 841806 **Description:** W 1/4 SEC COR 18 84 **Date Set:** 2/8/2006 **County:** Olmsted

Section: 18 **Township:** 108N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls on east side of CP to fences N-S-W
County Survey Disk in S side RR tie CP W 0.65'
County Survey Disk in W side 12" Walnut NNE 31.83'
Pk nail in 12" Walnut NNE 19.42'
Pk nail in 10" Walnut NE 9.46'
Pk nail in double 6" Walnut SSE 22.77'
Sign on CP 1/2' W
This corner is located by GPS reference stations "Reese A & Scheffler"

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor North between sections 13 and 18. 40.00 chs. Set quarter section post. Bur Oak 6 in. N4°E 502 lks. Bur Oak 12 in. N1°W 1065 lks.

5-1891 Thomas Fraser (P. 451 No. 435), County Surveyor, could not find the corner or any evidence of it. Set a stake and stone by its side on line and midway between the section corners. Set the 1/16th North midway and on line.

4-1903 Charles Armstrong (P. 49 B Plat only) shows a stake and stone at the corner, a stone midway at the 1/16th North, a stake at the center of section 13, and a stone at the W. 1/4 Cor. Of section 13.

4-1938 John Kerr (B. 12 P. 54), County Surveyor, "set boulder by stake and packed with rock broken". Set an iron midway and on line at the 1/16th North.

4-1938 John Kerr (B. 12 P. 60) shows a stone boulder at the corner.

10-27-1977 County Surveyor dug with the backhoe at the 1/16th North. Found a 5" x 10" x 26" limestone on the West side of an old stake. Also found a 3/4" x 30" pointed shaft 1.7' East and 1.45' North of the stake and a 3/4" pinched pipe inside a 1 1/4" pipe .2' East and .65' South of the stake.

10-1977 County Surveyor dug for the corner but did not find anything. The corner comes near a large new cresote corner post set in or over concrete.

11-5-1977 County Surveyor set a Cast Iron Cap on a square pipe. Corner on east side of corner post to fences N-S-W, .9E and .3N of traverse nail.

6-7-2001 County Surveyor found cast iron cap on telspar pipe up 0.9' leaning North.

6-26-2003 Johnson & Scofield found Cast Iron Cap on a square pipe up .9'. Straightened pipe in existing hole.

2-8-2006 County Surveyor found telspar w/CIC leaning, removed. Set 4 1/2' telspar w/CIC from computed coordinates up 0.3'. CSD with concrete nail in south side of RR tie set as corner post west 0.65'. CSD with 60d nail in west side of 10" Walnut NNE 31.35'. Sign nailed on north and south side of corner post.